

ANALYTICAL INDUSTRIAL RESEARCH LABORATORIES, INC.

1550 37TH STREET, NE
CLEVELAND, TENNESSEE 37312
(423) 476 - 7766 Fax: (423) 476-7714

North Carolina Certification# 340
Tennessee Certification# 02034
LELAP #AI85697

Lab Report 218418

7543
Sportex Construction Services
Attention: Phil Stricklen
197 Boling Industrial Way
Calhoun, GA 30701

Date Received 3/10/2009
Date Sampled 3/9/2009
Date Requested 3/13/2009
Rush Status Rush
Phone (706) 624-9680
Extension 311
 Fax (706) 624-9674
PO#

Sample Information

Sportex Strenex
S-9016 Turf Yarn

Lab Report	218418	Result	MDL	MCL	Method	Date	Time	Analyst
		Arsenic (As)	< 2	mg/Kg	2	6010	3/16/2009 12:30	IFH
		Barium (Ba)	0.826	mg/Kg	0.1	6010	3/16/2009 12:30	IFH
		Cadmium (Cd)	< 0.2	mg/Kg	0.2	6010	3/16/2009 12:30	IFH
		Chromium (Cr)	13.8	mg/Kg	0.25	6010	3/16/2009 12:30	IFH
		Lead (Pb)	9.47	mg/Kg	1.5	6010	3/16/2009 12:30	IFH
		Mercury (Hg)	< 0.21	ppm	0.21	7471B	3/17/2009 9:35	ADW
		Selenium (Se)	< 2.5	mg/Kg	2.5	6010	3/16/2009 12:30	IFH
		Silver (Ag)	< 0.5	mg/Kg	0.5	6010	3/16/2009 12:30	IFH
		Zinc (Zn)	574.2	mg/Kg	0.1	6010	3/16/2009 12:30	IFH

QA/QC Procedures required by the Method(s) were followed unless otherwise noted. Performance and acceptance standards for required QA/QC procedures were achieved unless otherwise noted. No significant modifications have been made to the Method(s). I attest that, based upon my inquiry of those individuals immediately responsible for reviewing the information, the material contained in this report is, to the best of my knowledge and belief, accurate and complete.

These results relate only to the items tested. This report shall not be reproduced except in full and with permission of this laboratory. The laboratory retains sole ownership of data until full reimbursement has been made.

Report approved by:
